

Facility Name: Utica Resource Operating, LLC – Mason Well Pad
Facility Location: 39.56775, -81.5891, Wills Township, Ohio
Date of Inspection: April 18, 2019

APPENDIX A: DIGITAL VIDEO LOG

1. Inspector Name: Victoria Nelson	2. Dates of Inspection: April 18, 2019
3. Company/Facility Name: Utica Resource Operating, LLC – Mason Well Pad	4. Street Address, City, State: 39.56775, -81.5891, Wills Township, Ohio
5. Number of Videos: 5	6. Archival Record Location: C:\Users\Vnelson\OneDrive - Environmental Protection Agency (EPA)\MyCases\Utica Resource\Inspection Reports

Video Number	File Name	Date	Description of Video
1	MOV_2411.mp4	4/18/2019	Emissions from tank battery - ground level view
2	MOV_2412.mp4	4/18/2019	Emissions from combustor stack
3	MOV_2413.mp4	4/18/2019	Emissions from 2-H gunbarrel tank header line pressure relief device
4	MOV_2414.mp4	4/18/2019	Emissions from Tank 2278 meter threaded connection
5	MOV_2415.mp4	4/18/2019	Emissions from Tank 2279 header line pressure relief device